

PUBLIC STREET SITE ANALYSIS

Initial Observations - 09.20.2022




OWNERSHIP (1:300)




Cargill Inc.	128
C.H. Sprague & Son Company	160
Petes Tire Barn of RI LLC	323
SMM New England Corp.	325, 326, 361, & 630
RI Energy	481, 489, & 501
Narragansett Improvement Corp.	314, 363, 600, & 603

ACCESS

MOBILITY (1:700)










Signage

SITE APPROACH

Public Street Animation





Public St - Landmarks

CULTURAL HISTORY

State Pier 01

New Building on the Port of Providence State Pier in 1915. Inspection rooms and immigrant headquarters are on the second floor. The front is occupied by an exceptional suite of offices. Thoroughly modern construction provides the maximum efficiency in freight and passenger handling. The sides of the building are so constructed that any section or number of segments between the piers of the frame can be hoisted and folded up in a moment, to accommodate the gangplanks hung from any portion of a steamer of any size

alongside.Providence Magazine, March 1915, P. 162. GGA Image ID # 131cOd3cc9




This distinct rise of the Italian American in Providence, is marked by a shift of immigration from the "old" northwestern to southwestern European immigration. For Rhode Island, immigrants were mainly Portuguese and Italian, and immigration patterns themselves were changed by the Chinese Exclusion and Passenger Acts of 1882.2 These acts restricted certain country's allowed immigration to the United States.

The Venezia, pictured left, was the first ship to visit a currently unfinished State Pier No. 1 on December 17, 1913.




PHYSICAL HISTORY NEIGHBORHOOD - 1939 - 2022


































PHYSICAL HISTORY SITE - 2018 - 2022

SITE FLOWS

TIDES



HIGH TIDE 1:10 PM Sept. 15, 2022



LOW TIDE 3:20 PM Aug. 12, 2022

TRAFFIC




Truck backing in 8:00AM Sept. 20, 2022

View from East Bay Bike Path Ship and Boat Traffic










Flag: USA


Call sign	IMO	MMSI
WDC3878	8987345	367015670
Length x breadth 28.04m x 5.4 9m		ear built



Speed: **0 kn**

Flag: Singapore

Call sign	IMO	MMSI
9V2557	9300221	564220000
Length x breadth		′ear built
189.9m x 32 <u>.26m</u>		•••





Status: **Moored** Received: **2' ago●** Speed: **0 kn**

Flag: **Portugal**

Call sign CQII9	IMO 9609718	MMSI 255721000
Length x breadth 187m x 28.6m		∕ear built
	le.	S 1 1 1 1



Views from Collier Point Park




SALT PILES SEPT. 16

Salt is stockpiled adjacent to the site for treating roads, streets, and sidewalks during snow, sleet, and freezing events. Recently, there has been increasing attention to the issue of salinity and how salt treated runoff can affect local waterways.



POLLUTANTS





Interactive Map with Real-time Status of Air Quality at Monitoring Sites Around the Port of Providence

12:30 PM Sept. 20, 2022

USES

USES (1:2000)



KEY V

 ∇


PUBLIC POINT OF ACCESS POTENTIAL POINT OF ACCESS



BOAT RAMPS, BAITSHOPS, AND MARINAS

BIKE PATH

KAYAK CANOE RAMP



PASSIVE RECREATION




NATURE WATCHING



BOAT/SHIP WATCHING





HABITAT RESTORATION



Port of Tacoma


Port Development: Integrating Mitigation and Habitat Restoration







SITE LEVEL ANALYSIS



PUBLIC STREET - SITE ANALYIS I

SEPTEMBER 20, 2022

THANK YOU QUESTIONS?